


# DIGITAL CONTROL OF POWER ELECTRONICS

## Current Mode Control of Buck Converter



The plant for a buck converter in continuous conduction mode is shown below.


$$G_p(s) = \frac{v_o}{i_L} = \frac{R(1 + srC)}{(1 + sRC)} \quad (1)$$

Note, the plant has a single pole and a single zero.

The parameters of the buck converter are shown below.

$$V_{in} = 30, V_o = 15, L = 200\mu H, C = 400\mu F, r = 0.1, R = 5 \quad (2)$$

The bode plot of the plant transfer function is shown below for various load points.



Design the controller below, find the zero, pole and gain for a bandwidth of  $f_c = 1\text{kHz}$  and phase margin of 60 degrees.

$$G_c(s) = \frac{k \left(1 + \frac{s}{\omega_z}\right)}{s \left(1 + \frac{s}{\omega_p}\right)} \quad (3)$$

Evaluate the gain of phase of the plant at the desired bandwidth

$$|G_p(s)|_{s=j\omega} \quad (4)$$

$$\angle G_p(s)|_{s=j\omega} \quad (5)$$

$$\phi_{boost} = -90^\circ + \phi_{PM} - \angle G_p(s)|_{s=j\omega} \quad (6)$$

$$k_{boost} = \tan\left(45^\circ + \frac{\phi_{boost}}{2}\right) \quad (7)$$

$$\omega_z = \frac{2\pi f_c}{k_{boost}} \quad (8)$$

$$\omega_p = 2\pi f_c k_{boost} \quad (9)$$

$$k = \frac{\omega_z}{|G_p(s)|_{s=j\omega}} \quad (10)$$

```

1 clear
2
3 Vin = 30
4 L = 200e-6
5 C = 400e-6
6 r = 0.1
7 R = 5
8
9 fc = 1000 % select bandwidth
10 pm = 60 % select phase margin
11 w = 2*pi*fc
12
13 gain_gps = abs(R*(1+j*w*r*C)/(1+j*w*R*C))
14 angle_gps = angle(R*(1+j*w*r*C)/(1+j*w*R*C))*180/pi
15
16 phiboost = -90 +pm-angle_gps
17 gain_need = 1/gain_gps
18
19 Kboost = tand(45+phiboost/2)
20 fz = fc/Kboost
21 fp = Kboost*fc
22 kc = 2*pi*fz/gain_gps
23
24 wz = 2*pi*fz
25 wp = 2*pi*fp

```

$$\omega_z = 2840 \quad \omega_p = 13897 \quad k = 6946 \quad (11)$$

