





# CUSP Course 7 – Handout 4


## Fractional Slot Winding Design – using star-of-slots




Phase B




Phase A




Phase C






**Phase A**



**Phase B**



**Phase C**

